

STAT

24 November 1964  
552 - CD-114  
AKC:rf

Parts Unacceptable to Customer, but not Supplied by [REDACTED]

STAT

1. Z-Axis

Customer comments: What [REDACTED] has provided does not fall within the design objective, and not adjustable by a seated operator.

STAT

2. Transparent Vacuum Edge

The operator must see the information on both edges, without magnification. The system is not usable with an opaque edge since he cannot see frame number.

3. Control Cabinet Height

Top desired to be the same as the working surface of the viewer.

4. Unacceptable Drive System

5. Color Temperature of Light Source, and Uniformity

6. Excessive Play in Eyepiece Mounting

7. Lens adjustment in the Interpupillary Adjustment

8. Need a Load on Top of the Eyepiece

9. Need a Longer Headrest Adjusting Screw

10. 552 ONLY

The vacuum system is not acceptable for 552 since the film cannot be moved, due to the requirement for mensuration.

DDR-DUPE